

Labor and Materials

1	Copper	Connection	\$	3.20
1	Curb	Cock T. & V.	in.	\$ 1.00
1	Service Box	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$ 1.30
30	Ft.	3/4 in. Copper Galv. Iron Cast Iron	Pipe at	\$ 6.16
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
1	Red Iron	Couplings	to in. at	\$
	Union	in. at	\$	
	Meter	in. at	\$	
	Lbs. Br. Stone	at	\$	
	Lbs. Sand	at	\$	
	Bags Cement	at	\$	
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at	\$	
	Leadite Joints	at	\$	
2	Hrs. Foreman	at	\$	12.5
1.0	Hrs. Common Labor	at	\$	4.05
	Hrs. Common Labor	at	\$	
	Hrs. Mason	at	\$	
	Hrs. Mason's Helper	at	\$	
	Hrs. Compressor	at	\$	
	Compensation Ins.		\$	1.4
2	Trucking		\$	1.05
25	Builders' Use of Water		\$	
Total				\$ 181.0

31 STATE
2/05

West

Labor and Material Report Dec 18 1925

2 State St

Curb Box

BUSH ST

6" Main Elev. of Main at tap 5'

Gate at 28' to main Gate at 3/4" copper

Curb Box

Wayne V. Merrill
1965
Bush St. End

Merrill

Tax records list above
property as 31 W. State
TAX ID 309.15-14-7