

Labor and Materials

Copper } Connection.....	3	\$ 2.60
Lead }		
Curb } Cock Valve }	3	\$ 2.27
T.S. & V. }		
Service Box } Short 3/2x1 1/2 }		\$ 1.38
Old returned } Long 4 1/2x5 1/2 }		
Buff. or Rdway }		
9 Ft. } in. } Copper } Pipe at.....	2	\$ 1.62
Galv. Iron }		
Cast Iron }		
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g }		
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement 'at.....		\$
Paving Brick } Mack } at.....		\$
Red }		
Asphalt }		
Lead Joints at.....		\$
Leadite Joints at.....		\$
2 Hrs. Foreman at.....		\$ 1.25
8 Hrs. Common Labor at.....		\$ 3.60
Hrs. Common Labor at.....		\$
Hrs Mason at.....		\$
Hrs Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$.15
Trucking.....		\$ 1.-
Builders' Use of Water.....		\$ 5.-
Total \$.....		\$ 18.97

31-21
Labor and Material Report April 20 1931
 13 Stewart Ave.

House 32' 10" Porch HOUSE 32' 10" Curb Box

6 Main Eley of Main at tap 5'

Gate at ● Gate at ●
 3/4" Copper 9' to MAIN

● Curb Box

Old tap disconnected

TAX ID# 309.12-15-12