

Labor and Materials


1	Copper	Connection	3/4		\$ 3.20
	Lead				
1	Curb	Cock Valve	2 1/2	in.	\$ 1.00
		F. S. & V.			
1	Service Box	Short 3 1/2 x 4 1/2			\$ 14.00
	Old returned	Long 4 1/2 x 5 1/2			
		Buff. or Rdway			
2 1/2	Ft.	3/4 in. Copper		Pipe at	\$ 5.94
		Galv. Iron			
		Cast Iron			
	Nipples			in. at	\$
	Bushings			to in. at	\$
1	Red g Inch	Couplings	2	to in. at	\$ 1.50
	Union			in. at	\$
	Meter			in. at	\$
	Lbs. Br. Stone	at			\$
	Lbs. Sand	at			\$
	Bags Cement	at			\$
	Paving Brick	Mack		at	\$
		Red			\$
		Asphalt			\$
	Lead Joints	at			\$
	Leadite Joints	at			\$
2	Hrs. Foreman	at	2.5		\$ 1.25
1.2	Hrs. Common Labor	at	5.0		\$ 6.00
	Hrs. Common Labor	at			\$
	Hrs. Mason	at			\$
	Hrs. Mason's Helper	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.				\$ 2.00
	Trucking				\$ 1.00
	Builders' Use of Water				\$

Total \$ 20.14

26-63

Labor and Material Report June 28 19

28 Street



30.2
32.8
T. 4
Curb Box 32" 5"

6 Main Elev. of Main at tap 3

Gate at 3/4" copper 27' to main Gate at

Curb Box

Water Tap

TAY ID# 309.15-3-6