

Labor and Materials

1	Copper	Connection	3	\$ 1.48
1	Lead			
7	Curb	Cock Valve T.S. & V.	3	\$ 1.79
1	Service Box	Short 3 1/2 x 4 1/2		\$ 1.30
	Old returned	Long 4 1/2 x 5 1/2		
		Buff. or Rdwr.		
27	Ft.	Copper Pipe at	3/4	\$ 4.86
		Cast Iron		
		Nipples		\$
		Bushings		\$
		Red'g Inc'g		\$
		Couplings		\$
		Union		\$
		Meter		\$
		Lbs. Br. Stone		\$
		Lbs. Sand		\$
		Bags Cement		\$
		Paving Brick		\$
		Lead Joints		\$
		Leadite Joints		\$
4	Hrs.	Foreman		\$ 2.50
10	Hrs.	Common Labor		\$ 4.50
		Hrs. Common Labor		\$
		Hrs. Mason		\$
		Hrs. Masons Helper		\$
		Hrs. Compressor		\$
		Compensation Ins		\$
		Trucking		\$ 1.00
		Builders Use of Water	Patrol (Suwr)	\$ 2.50
Total \$				

32-92

Labor and Material Report *Aug* 13, 1932

30 *Stewart Ave.*

24'7" 25'6" 25'6"

● Curb Box

6 Main Elev. of Main at tap $4\frac{1}{2}$

Gate at ● *3/4" Copper* 27' to MAIN ● Gate at

● Curb Box

New House.

No Measurements.

TAX ID # 309.15-3-7

OK [Signature]