

LABOR AND MATERIALS

Copper Lead	{ Connection	-----	\$
Curb	{ Cock Valve T. S. & V.	----- in.	\$
Service Box	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	-----	\$
Old returned		-----	\$
Ft. ----- in.		{ Copper Galv Iron Cast Iron	Pipe at
Nipples	in. at	-----	\$
Bushings	to ----- in. at	-----	\$
Red'g Inc'g	{ Couplings	to ----- in. at	\$
Union	in. at	-----	\$
Meter	in. at	-----	\$
Lead Joints	at	-----	\$
Leadite Joints	at	-----	\$
Hrs. Foreman	at	-----	\$
Hrs. Chauffeur	at	-----	\$
Hrs. Tapper	at	-----	\$
Hrs. Labor	at	-----	\$
Hrs. Labor	at	-----	\$
Hrs. Compressor	at	-----	\$
Compensation Ins.	-----	-----	\$
Trucking	-----	-----	\$
Builders Use of Water	-----	-----	\$
		-----	\$
		-----	\$
		-----	\$
		-----	\$
		-----	\$

St.
Pt.
Ave. No. 36

Stewart

Name of Owner
Home Owners' Loan Corp.

Labor and Mat'l. Report Dec. 31 1938

Stewart Ave

Staple at

Main Elev. of Main at tap

Gate at ● ● Gate at

TAX ID # 309.15-3-10

● Curb Box