

Labor and Materials

1	Copper } Connection	3	\$3.20
	Lead } Connection	4	
1	Curb } Cock Valve T. S. & V. } 3/4 in.	4	\$1.00
1	Service Box } Short 3 1/2 x 4 1/2 } Old returned } Long 4 1/2 x 5 1/2 } Buff. or Rdway }		\$1.40
26	Ft. } 3/4 in. } Copper } Galv. Iron } Cast Iron } Pipe at		\$5.72
	Nipples	in. at	\$
	Bushings	to in. at	\$
1	Red } Couplings } 3/4 to 1 in. at		\$.15
	Union	in. at	\$
	Meter	in. at	\$
	Lbs Br. Stone at		\$
	Lbs Sand at		\$
	Bags Cement at		\$
	Paving Brick } Mack } Red } Asphalt }	at	\$
	Lead Joints at		\$
	Leadite Joints at		\$
3	Hrs. Foreman at	6.25	\$1.88
12	Hrs. Common Labor at	40.78	\$4.87
	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
	Hrs. Compressor at		\$
	Compensation Ins.		\$.19
	Trucking		\$ 1.00
	Builders' Use of Water		\$
Total			\$20.21

26-19
Labor and Material Report May 10 1926

10 Stewart Ave



6 Main

Elev. of Main at tap 4'

Gate at

3/4" Copper

26' to main Gate at

Curb Box

New Tap

New House

TAX ID# 309.161-8