

Labor and Materials

1	Copper	} Connection ^{3/4"}	\$ 1.48
	Lead			
1	Curb	{ Cock Valve } ^{3/4"}in\$ 1.79
1	Service Box	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rawl.	\$ 1.30
	Old returned			
10	Ft. ^{3/4"} in.	{ Copper Galv. Iron } Pipe at	\$ 1.80
		{ Cast Iron		
	Nipplesin. at	\$
	Bushingstoin. at	\$
	Red'g Inc'g	{ Couplings.....toin. at	\$
	Unionin. at	\$
	Meterin. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	{ Mack Red Asphalt } at	\$
	Lead Joints		at
	Leadite Joints	at	\$
5	Hrs. Foreman	at	\$ 7.25
1	Hrs. Common Labor	at ^{Blacksmith}	\$ 2.15
4	Hrs. Common Labor	at	\$ 1.80
	Hrs. Mason	at	\$
	Hrs. Masons Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins	\$ 2.22
	Trucking	\$ 1.00
	Builders Use of Water	^{Patch}	\$ 5.00
Total \$				19.79

522-57
Labor and Material Report ^{Jan 2} 1932

3/4" tap at 11 Stewart Ave



6 Main
Elev. of Main at tap ^{44.1'}
Gate at ^{3/4"} 10' to MAIN
Gate at
Curb Box

Old tap shut off

TAX ID # 309.12-15-13

OK [initials]