

Labor and Materials

1	Copper } Connection.....	\$ 3.20
	Lead }	
1	Curb } Cock }	\$ 1.00
	Valve } T. S. & V. }	
1	Service Box } Short 3 1/2 x 4 1/2 }	\$ 1.30
	Old returned } Long 4 1/2 x 5 1/2 }	
		Buff. or Rdway }
6	Ft. } in. } Copper } Pipe at. 2 1/2	\$ 13.20
		Galv. Iron }
		Cast Iron }
	Nipples } in. at.	\$
	Bushings } to. in. at.	\$
	Red'g } Couplings } to. in. at.	\$
	Inc'g }	
	Union } in. at.	\$
	Meter } in. at.	\$
	Lbs. Br. Stone at.	\$
	Lbs. Sand at.	\$
	Bags Cement at.	\$
	Paving Brick } Mack } at.	\$
		Red }
		Asphalt }
	Lead Joints at.	\$
	Leadite Joints at.	\$
1	Hrs. Foreman at. 62.5	\$ 6.30
2	Hrs. Common Labor at. 50	\$ 1.00
	Hrs. Common Labor at.	\$
	Hrs. Mason at.	\$
	Hrs. Mason's Helper at.	\$
	Hrs. Compressor at.	\$
	Compensation Ins.	\$.05
	Trucking }	\$ 1.00
	Builders' Use of Water.	\$
Total		\$ 9.60

26-178

24

Labor and Material Report

Oct 26

1926

3/4 tap at 18 feet from main



6 Main Elev. of Main at tap

Gate at Gate at

3/4 Copper Conn 6' to MAIN

Curb Box

TAX ID # 302.12-7-23