LABOR AND MATERIALS

1	Copper ~~Lead~~ Connection	$1.23
1	Curb { Cock ~~Valve~~ ~~T. S. & V.~~ } ____ in.	$1.68
1	Service Box ~~Old returned~~ { Short 3½x4½ ~~Long 4½x5½~~ ~~Buff. or Rdway~~ }	$1.54
8	Ft. ¾ in. { Copper ~~Galv Iron~~ ~~Cast Iron~~ } Pipe at	$1.36
	Nipples ____ in. at	$
	Bushings ____ to ____ in. at	$
	Red'g Inc'g Couplings ____ to ____ in. at	$
	Union ____ in. at	$
	Meter ____ in. at	$
	Lead Joints at	$
	Leadite Joints at	$
	Hrs. Foreman at	$
3	Hrs. Chauffeur at 62½¢	$1.88
8	Hrs. Tapper at	$5.00
8	Hrs. Labor at .45	$3.60
	Hrs. Labor at	$
	Hrs. Compressor at	$
	Compensation Ins.	$.32
	Trucking	$1.—
	Builders Use of Water no patch	$
	Taplay Hessel	$
		$
		$
		$
		$17.61

8 - - 1939

St. ~~Pl.~~ 30

Terra Cotta Ave. No. 24

Name of Owner

Garner Tripp

Labor and Mat'l. Report April 10 1939

6" Main

Elev. of Main at tap 4½'

Gate at ● ● Gate at

¾" copper 8' to main

● Curb Box

TAX ID # 302.12-7-25

Old tap disconnected.

Tap made by Hessel.