

Labor and Materials

1	Copper Lead	Connection $3/4"$	\$ 3.20
1	Curb	Cock Valve T-S & V. $3/4"$ in.	\$ 1.00
1	Service Box	Short $3 1/2 \times 4 1/2$	\$ 1.20
	Old returned	Long $4 1/2 \times 5 1/2$ Buff. or Rdway	
22	Ft. $3/4"$ in.	Copper Galv. Iron Cast-iron	Pipe at \$ 4.84
	Nipples	in. at	\$
	Bushings	to in. at	\$
1	Red'g Lock	Couplings $1/2"$ to $1/2"$ in. at	\$ 1.15
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	Mack Red Asphalt at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
5	Hrs. Foreman	$6 2/3$	\$ 3.13
1	Hrs. Common Labor	$40 2/3$	\$ 4.88
	Hrs. Common Labor	at	\$
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$ 1.21
	Trucking		\$ 1.00
	Builders' Use of Water		\$

Total \$ 19.77

78-44 33

Labor and Material Report May 22 1928

$3/4"$ tap at $29'$ ~~Terminal Ave~~



6" Main Elev. of Main at tap 5
 Gate at ● Gate at ●
 $3/4"$ COPPER 22' to MAIN

● Curb Box

Old tap shut off

TAX ID# 302.12-10-3