

LABOR AND MATERIALS

1	Copper Lead	{ Connection $\frac{3}{4}$ in.	\$ 1.23
1	Curb	{ Cock Valve T. S. & V. } $\frac{3}{4}$ in.	\$ 1.68
1	Service Box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway }	\$ 1.54
12 Ft. $\frac{3}{4}$	in.	{ Copper Galv. Iron Cast Iron } Pipe at 17	\$ 2.04
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	{ Couplings to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
	Hrs. Foreman	at	\$
4	Hrs. Chauffeur	at $6 \times \frac{1}{2}$	\$ 2.50
4	Hrs. Tapper	at 7	\$ 2.50
6	Hrs. Labor	at 45	\$ 2.70
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$.24
	Trucking		\$ 1.00
	Builders Use of Water (no patch)		\$
Total			\$ 15.43

89 - - 1939

St. 3

Pt. 5

Ave. No. 5

Name of Owner

F. D. Kimball

Labor and Mat'l. Report

Sept 7

1939



6 Main

Elev. of Main at tap 6

Gate at ●

● Gate at

3/4 COPPER

12' to main

● Curb Box

TAX ID# 309.12-10-4

Take Billied

old sheet off