

Labor and Materials

Copper	}	Connection	\$		
Lead						
Curb	}	Cock in	\$		
		Valve				
		T. S. & V.				
Service Box	}	Short 3½ x 4½	\$		
Old returned		Long 4½ x 5½				
		Buff. or Rdway				
Ft. in.	}	Copper	Pipe at	\$		
		Galv Iron				
		Cast Iron				
Nipples in. at			\$		
Bushings to in. at		\$		
Red'g	}	Conplings to in. at	\$	
Inc'g						
Union in. at			\$		
Meter in. at			\$		
Lead Joints	at			\$		
Leadite Joints	at			\$		
Hrs. Foreman	at			\$		
Hrs. Chauffeur	at			\$		
Hrs. Tapper	at			\$		
Hrs. Labor	at			\$		
Hrs. Labor	at			\$		
Hrs. Compressor	at			\$		
Compensation Ins.				\$		
Trucking				\$		
Builders Use of Water				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		

St.
Pt.
Ave. No.

third

Name of Owner *Murphy*

Labor and Mat'l. Report *April 7-38* 19

Q.H.Y.D. Right side Street



left side

● Curb Box

..... Main Elev. of
Main at tap.....

Gate at ● ● Gate at

● Curb Box

*On City Hall records
as on Big Cross St.*