

**Labor and Materials**

Copper } Connection.....	3	\$ 96
Lead } .....	2	
Curb { Cock } .....	3	\$ 1.33
{ Valve } .....	4	
{ T.S.&V. } .....		
Service Box { Short 3 1/2 x 4 1/2 } .....	4	\$ 1.35
Old returned { Long 4 1/2 x 5 1/2 } .....		
{ Buff. or Rdway } .....		
17 Ft. .... in. { Copper } Pipe at 15		\$ 2.55
{ Galv. Iron } .....		
{ Cast Iron } .....		
Nipples ..... in. at .....		\$ .....
Bushings ..... to ..... in. at .....		\$ .....
Red'g } Couplings..... to ..... in. at .....		\$ .....
Inc'g } .....		
Union..... in. at .....		\$ .....
Meter..... in. at .....		\$ .....
Lbs. Br. Stone at .....		\$ .....
Lbs. Sand at .....		\$ .....
Bags Cement at .....		\$ .....
Paving Brick { Mack } at .....		\$ .....
{ Red } .....		
{ Asphalt } .....		
Lead Joints at .....		\$ .....
Leadite Joints at .....		\$ .....
Hrs. Foreman at .....		\$ .....
Hrs. Common Labor at .....		\$ .....
Hrs. Common Labor at .....		\$ .....
Hrs. Mason at .....		\$ .....
Hrs. Masons Helper at .....		\$ .....
Hrs. Compressor at .....		\$ .....
Compensation Ins .....		\$ .....
Trucking .....		\$ .....
Builders Use of Water Patch		\$ 5-
Total \$.....		

Labor and Material Report

19

50 Third St



Main

Elev. of Main at tap

Gate at

3/4" copper

17'

Gate at

MAIN

Curb Box

old shut off at main  
TAX ID# 309.11.11-6