

LABOR AND MATERIALS

1	Copper Lead	{ Connection	$\frac{3}{4}$		\$ 1.23
1	Curb	{ Cock Valve I.S. & V.	$\frac{3}{4}$	in.	\$ 1.68
1	Service Box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway			\$ 1.54
9	Ft. $\frac{3}{4}$ in.	{ Copper Cast Iron		Pipe at 17	\$ 1.53
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	{ Couplings	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Leadite Joints	at			\$
	Hrs. Foreman	at			\$
4	Hrs. Chauffeur	at	62hr		\$ 2.50
4	Hrs. Tapper	at			\$ 2.50
6	Hrs. Labor	at	45		\$ 2.70
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.				\$ .24
	Trucking				\$ 1
	Builders Use of Water	no patch			\$
	Taphy Penon				\$
					\$
					\$
					\$
					\$
					\$ 14.92

91 -- 1939

St.

Pt.

Ave. No.

Third

7

Name of Owner

Catherine Lynch

Labor and Mat'l. Report

Sept 8

1939



● Curb Box

6 Main

Elev. of Main at tap 5

Gate at ●

● Gate at

$\frac{3}{4}$ " Copper

9' to main

● Curb Box

TAX ID# 309.12-10-39

To be Billed

old shut off