

LABOR AND MATERIALS

1	Copper	Connection	3/4		\$ 2.94
	Lead				
1	Curb	Cock Valve	3/4	in.	\$ 3.71
		T. S. & V.			
1	Service box	Short 3/2 X 3/2			
	Old returned	Long 4 1/2 X 5 1/2			\$ 5.90
		Buff or Rdway			
8	Ft.	3/4 in. Copper Pipe at	30		\$ 2.40
		G.I.			
		G.I.			
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g				
	Inc'g	Coupl'gs. to in. at			\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
1	Hrs. Water Maint. Man-1	at			\$ 1.12
1	Hrs. Water Maint. Man-2	at			\$ 1.02
3	Hrs. Labor-	at			\$ 2.73
	Hrs. Labor-	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.	at \$ 2.20 per C.			\$ 1.11
	Trucking				\$ 1.11
	Pav't Patch				\$
	Tap by 1422 units				\$
	O'head				\$
					\$ 20.93

81

St.
Pl.
Ave. No. 87

Third

Name of Owner

Sweet

Labor and Mat'l. Report Nov 10 19 48



● Curb Box

6 Main Elev. of Main at tap 8

Gate at ● ● Gate at

3/4" Copper 8' to main

● Curb Box

TAX ID # 309.11-5-51

LSM-5C 5 15-48 This tap in Double Head