

WATER DEPARTMENT

City of Glens Falls, New York

May 18 19 49

A. M. P. M.

Mr. Douglasy 3/10p

Tel. Call: 93 Third St

Turn on: Sweet + Sour

Shut off:

Leak:

Misc:

Hyd 3120

REMARKS:

6" Main 6 ft Deep
12 ft of 3/4" copper pipe
10 ft by 2" diameter
May 18 49 6.12

By: [Signature] From: [Signature] To:

33

St. Third Ave. No. 93

Name of Owner

Sweet

Labor and Mat'l. Report

May 18 19 49

● Curb Box

6 Main

Elev. of Main at tap 6

Gate at ●

● Gate at

3/4" copper 12' to main

● Curb Box

LABOR AND MATERIALS

1. Copper / Lead Connection	3/4		\$ 2.87
1. Curb / Valve / T-S & y.	3/4	in.	\$ 3.62
1. Service box / Old returned	Short 3/2 X 4 1/2 / Long 4 1/2 X 5 1/2		\$ 4.68
12. Ft. 3/4 in. Copper / G.I. / C.I.		Pipe at 32	\$ 3.84
Nipples	in. at		\$
Bushings	to in. at		\$
Red'g / Inc'g Coupl'gs	to in. at		\$
Union	in. at		\$
Meter	in. at		\$
Lead Joints at			\$
Compound Joints at			\$
Hrs. Water Maint. Man—1 at			\$
1. Hrs. Water Maint. Man—2 at	1.02		\$ 1.02
4. Hrs. Labor— at	91		\$ 3.64
Hrs. Labor— at			\$
Hrs. Compressor at			\$
Compensation Ins. at \$		per C.	\$ 10
Trucking			\$ 2
Pav't Patch			\$
O'head			\$
			\$ 21.77