

WATER DEPARTMENT

City of Glens Falls, New York

May 18 19 19

A. M. P. M.

Mr. Douglass 3/ Top

Tel. Call: 95 Third St

Turn on: Sweet + Sower

Shut off:

Leak:

Misc:

CRIBSON 240' 9" 0

REMARKS:

6" Main 6 ft Deep
25 ft of 3/4" copper pipe
10 ft of 1/2" galvanized
May 18 1919 L.B.

By: [Signature] From: [Signature] To:

34

Third

St. Ave. No. 94

Name of Owner

Sweet

Labor and Mat'l. Report May 18 19 19

● Curb Box

6 Main Elev. of Main at tap 6

Gate at ● Gate at

3/4" Copper 25' to main

● Curb Box

TAX ID # 309.11-9-5

LABOR AND MATERIALS

1	Copper	Connection	3/4		\$	2.87
1	Curb	Cock Valve	3/4	in.	\$	3.62
		P. S. & V.				
1	Service box	Short	3 1/2 X 4 1/2			4.68
	Old returned	Long	4 1/2 X 5 1/2			
		Buffer Rdway			\$	
25	Ft.	3/4	in.	Copper	Pipe at	32
				G. I.		8.00
				C. I.		
	Nipples	in.	at		\$	
	Bushings	to	in.	at	\$	
	Red'g					
	Inc'g	Coupl'gs	to	in.	at	\$
	Union	in.	at		\$	
	Meter	in.	at		\$	
	Lead Joints	at			\$	
	Compound Joints	at			\$	
	Hrs. Water Maint. Man	—1	at		\$	
1	Hrs. Water Maint. Man	—2	at	1.02	\$	1.02
4	Hrs. Labor	—	at	91	\$	364
	Hrs. Labor	—	at		\$	
	Hrs. Compressor	at			\$	
	Compensation Ins.	at \$		per C	\$	10
	Trucking				\$	2-
	Pav't Patch				\$	
	Tip	4			\$	
	O'head				\$	
						\$25.93

6" MAIN

6' DEEP