

Labor and Materials

1	Copper } Connection $3/4"$	\$ 2.60
	Lead	
1	Curb } Cock Valve F-S & V. } $3/4"$ in.	\$ 2.27
1	Service Box } Short $3/4 \times 1/2$ } Old returned } Long $4 \times 5/8$ } Buff. or Rdway }	\$ 1.38
23	Ft. $3/4"$ in. } Copper Galv. Iron } Pipe at	\$ 4.14
	Cast Iron	
	Nipples in. at	\$
	Bushings to in. at	\$
	Red'g } Couplings to in. at	\$
	Inc'g }	
	Union in. at	\$
	Meter in. at	\$
	Lbs. Br. Stone at	\$
	Lbs. Sand at	\$
	Bags Cement at	\$
	Paving Brick } Mack } Red } Asphalt }	\$
	at	\$
	Lead Joints at	\$
	Leadite Joints at	\$
6	Hrs. Foreman at	\$ 3.75
12	Hrs. Common Labor at	\$ 5.40
	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. Mason's Helper at	\$
	Hrs. Compressor at	\$
	Compensation Ins.	\$.28
	Trucking	\$ 1.00
	Builders' Use of Water	\$ 5.00
	<i>Patch</i>	\$
	Total	\$ 25.82

27-83

Labor and Material Report July 27 1931

126 Third St. $3/4"$ tap



6" Main Elev of Main at tap 4.15

Gate at $3/4"$ copper 23' to main Gate at

● Curb Box

Old tap to be dug up

No charge for digging up old tap

TAX ID# 309.12-13-9