

# LABOR AND MATERIALS

1	Copper	Connection	3/4	\$	2.29
1	Lead				
1	Curb	Cock Valve	3/4 in.	\$	2.70
		F. S. & V.			
1	Service box	Short 3 1/2 x 4 1/2		\$	4.25
	Old returned	Long 4 1/2 x 5 1/2			
		Buff or Rdway			
9	Ft.	Copper	Pipe at 35	\$	3.15
	3/4 in.	G. I.			
		G. I.			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	Coupl'gs to in. at		\$	
	Inc'g			\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Hrs. Water Maint. Man-1	at		\$	
3	Hrs. Water Maint. Man-2	at 1.07		\$	3.06
3	Hrs. Labor	at 21		\$	273
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins. at \$	per C.		\$	13
	Trucking			\$	1.00
	Pav't Patch			\$	
	Tap by McQuinn			\$	
	O'head			\$	
				\$	19.31

Corner Fifth  
+  
Thomas St.

St.  
Pl.  
Ave. No.

---

Name of Owner  
Shappy

---

Labor and Mat'l. Report June 5 1958

44'3"      33'3"

● Curb Box

---

12 Main      Elev. of Main at tap 5-

Gate at ●      ● Gate at

3/4" copper      9' to main

---

● Curb Box

LSM-5C 10-21-49