

LABOR AND MATERIALS

1	Copper	{ Connection	3/4			\$ 2.29
	Lead					
1	Curb	{ Cock Valve	3/4	in.		\$ 2.70
		{ T.S. & V.				
1	Service box	{ Short 3 1/2 x 4 1/2				
	Old returned	{ Long 4 1/2 x 5 1/2				
		{ Buff or Rdway				\$ 4.25
10	Ft.	{ Copper	3/4	in.		
		{ G.I.				
		{ C.I.				
		Pipe at	35			\$ 3.50
	Nipples	in. at				\$
	Bushings	to in. at				\$
	Red'g	{ Coupl'gs		to in. at		\$
	Inc'g					\$
	Union	in. at				\$
	Meter	in. at				\$
	Lead Joints at					\$
	Compound Joints at					\$
2	Hrs. Water Maint. Man-1	at	1.12			\$ 2.24
	Hrs. Water Maint. Man-2	at	0			\$
2	Hrs. Labor	at	91			\$ 1.82
	Hrs. Labor	at				\$
	Hrs. Compressor at					\$
	Compensation Ins. at \$	per C.				\$ 1.09
	Trucking					\$
	Pav't Patch					\$
						\$
						\$
						\$
	O'head					\$
						\$ 17.89

Top of Miller

St. _____
 Pl. _____
 Ave. No. _____

Thomas

Name of Owner _____
Havens

Labor and Mat'l. Report *May 3* 1950

1 2 Main

Gate at ●

Elev. of Main at tap *5'*

● Gate at

3/4" Copper

10' to main

● Curb Box

LSM-5C 10-21-49