

Labor and Materials

1	Copper	Connection	3	\$ 1.33
1	Curb	Cock Valve	1	\$ 1.58
		Service Box		\$ 1.36
		Old returned		
10	Ft.	3 in. Copper Pipe at		\$ 9.5
		Nipples		\$
1	Bushings	1/2 to 3/4 in. at		\$.05
	Red'g Inc'g	Couplings	1	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
3	Hrs. Foreman	at	1.88	\$
8	Hrs. Common Labor	at	4.00	\$
8	Hrs. Common Labor	at	3.60	\$
	Hrs. Mason	at		\$
	Hrs. Masons Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins		.79	\$
	Trucking		1.50	\$
	Builders Use of Water	Patch	5.00	\$
Total				\$ 21.04

33-65 22 Aug 21 1933

Labor and Material Report

19 Thompson Ave

6 Main Elev. of Main at tap 5.2

Gate at 3/4 copper Gate at 10' to main

● Curb Box

Old tap shut off at main

TAX ID # 302.16-1-3

D.H.O.