

Labor and Materials

1	Copper } Connection ^{3/4}	\$ 1.25
1	Lead }	
1	Curb { Cock } ^{3/4} in	\$ 1.70
	{ Valve }	
	{ T.S.&V. }	
1	Service Box { Short 3 1/2 x 4 1/2 }	\$ 1.37
	{ Long 4 1/2 x 5 1/2 }	
	Old returned { Buff. or Rdwex }	
11	Ft. ^{3/4} in. { Copper } Pipe at 12 pr. \$ 1.49	
	{ Galv. Iron }	
	{ Cast Iron }	
	Nipples in. at	\$
	Bushings to in. at	\$
	Red'g } Couplings..... to in. at	\$
	Inc'g }	
	Union..... in. at	\$
	Meter..... in. at	\$
	Lbs. Br. Stone at	\$
	Lbs. Sand at	\$
	Bags Cement at	\$
	Paving Brick { Mack } at	\$
	{ Red }	
	{ Asphalt }	
	Lead Joints at	\$
	Leadite Joints at	\$
4	Hrs. Foreman at ^{6 1/2}	\$ 2.50
13	Hrs. Common Labor at ⁴⁵	\$ 5.85
	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. Masons Helper at	\$
	Hrs. Compressor at	\$
	Compensation Ins ³²	\$
	Trucking ^{1.15}	\$
	Builders Use of Water .. Patch ⁵⁻	\$

Total \$20.48

1935-101

36

Labor and Material Report Aug 28

19 35

3/4" Copal 36 Thomson Ave



6" Main

Elev of Main at tap 47.4

Gate at

3/4" copper 11' to main

Gate at

Curb Box

Old top shut off at main

Handwritten signature

TAX ID# 302.16-1-11