

### LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$	276
1	Curb	Cock Valve	3/4" in.	\$	249
Same T. S. & V.					
	Service box	Short 3 1/2 X 4 1/2		\$	
	Old returned	Long 4 1/2 X 5 1/2		\$	
		Buff or Rdway		\$	
8	Ft.	3/4" in.	Copper Pipe at	38	\$ 304
			C.I.		
			C.I.		
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g			\$	
	Inc'g	Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Hrs. Water Maint. Man-1	at		\$	
6	Hrs. Water Maint. Man-2	at	1.24	\$	244
14	Hrs. Labor	at	1.13	\$	1582
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.	at \$ 4.406 per C		\$	107
	Trucking			\$	100
	Pav't Patch			\$	10.80
	Tap by Giggard	7-6-53		\$	
	O'head			\$	
				\$	45.37

34.07

45.53

Thomson

St. \_\_\_\_\_  
Pl. \_\_\_\_\_  
Ave. No. 12

Name of Owner \_\_\_\_\_

Spector

Labor and Mat'l. Report July 6 19 53

25'-7"      21'-8"

● Curb Box

---

6" Main

Elev. of Main at tap 5 1/2'

Gate at ●      ● Gate at

3/4" Copper 8' to main

● Curb Box

TAX ID# 302.15-8-10

LSM-5C 5 15-48