

## LABOR AND MATERIALS

1	Copper } Connection	1 1/2	\$	
	Lead			
1	Curb { Clock Valve } T. S. & V. }	1 1/2 in.	\$	
1	Service box } Old returned }	Short 3 1/2 X 4 1/2 } Long 4 1/2 X 5 1/2 } Buff or Rdway }	\$	
22	Ft. 1 1/4 in. }	Copper } Galv. Iron } Cast Iron }	Pipe at	\$
	Nipples	in. at	Close Brass	\$
	Bushings	to	in. at (Brass)	\$
	Red'g } Inc'g }	Couplings	to	in. at
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints at			\$
	Compound Joints at			\$
	Hrs. Foreman at			\$
	Hrs. Chauffeur at			\$
	Hrs. Tapper at			\$
	Hrs. Labor at			\$
	Hrs. Labor at			\$
	Hrs. Compressor at			\$
	Compensation Ins.			\$
	Trucking			\$
	Builders Use of Water			\$
	Tap & Meter Aug 22, 46			\$
	1-1 1/2" Nip 6" long			\$
	1-1 1/2" Tee			\$
	1-1 1/2" "			\$
	3-3/4" Nipple 4" long	} all Brass		\$
	3-3/4" Curb each			\$
	3-3/4" adapters			\$
	3- Curb Boxes			\$
	2- 3/4" Ell			\$

96-46 ✓  
 St. \_\_\_\_\_  
 Pl. \_\_\_\_\_  
 Ave. No. 2-2 1/2 9

---

Name of Owner  
Ricciardellet Marchi Tall

---

Labor and Mat'l. Report Aug 22 1946

● Curb Box

---

6" C.I. 1965 Traver St.  
4" Gal Main      Elev. of Main at tap 6'

---

Gate at ●      ● Gate at

1 1/2" Copper Conn.      22' to MAIN

---

● Curb Box

This Tap on Traver St.

TAX ID # 303.17-8-1

LSM-5C-6-1-45