

Labor and Materials

Copper } Connection.....	3	\$ 2.70
Curb } Cock Valve }	4	\$ 2.39
	T. S. & V. }	
Service Box } Short 3/4 x 1/2 }	11	\$ 1.45
Old returned } Long 1/2 x 5/8 }		
	Buff. or Rdway }	
10 Ft. in. } Copper }	3	\$ 2.70
	Galv. Iron } Pipe at	
	Cast Iron }	
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g }		
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick } Mack } at.....		\$
	Red }	
	Asphalt }	
Lead Joints at.....		\$
Leadite Joints at.....		\$
3 Hrs. Foreman at.....	1.88	\$
11 Hrs. Common Labor at.....	4.95	\$
Hrs. Common Labor at.....		\$
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....	21	\$
Trucking.....	1	\$
Builders' Use of Water.....	5.-	\$
	Patch	
Total \$	22.28	

30-37
Labor and Material Report 7 1930
~~10-10-37~~ #13

6" C.I. 1965.
 Main Elev of Main at tap 55
 Gate at Gate at
 10' to MAIN
 Curb Box
 Old tap shut off
 TAX ID# 303.17-1-31