

## LABOR AND MATERIALS

1. Copper Connection $3/4$ in. ....	\$ 2.94
1. Lead Cock Valve T. S. & V. $3/4$ in. ....	\$ 3.71
1. Service box Old returned Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buffer Rdway	\$ 5.90
28 Ft. $3/4$ in. Copper Pipe at 30	\$ 8.40
..... Nipples ..... in. at .....	\$ .....
..... Bushings ..... to ..... in. at .....	\$ .....
..... Red'g Inc'g Coupl'gs ..... to ..... in. at .....	\$ .....
..... Union ..... in. at .....	\$ .....
..... Meter ..... in. at .....	\$ .....
..... Lead Joints at .....	\$ .....
..... Compound Joints at .....	\$ .....
1. Hrs. Water Maint. Man-1 at 1.12	\$ 1.12
3. Hrs. Water Maint. Man-2 at 1.02	\$ 3.06
1.0. Hrs. Labor- ..... at 91	\$ 9.10
..... Hrs. Labor- ..... at .....	\$ .....
..... Hrs. Compressor at .....	\$ .....
..... Compensation Ins. at \$ ..... per C. ....	\$ 29.
..... Trucking .....	\$ 1.00
..... Pav't Patch .....	\$ .....
..... Tap by <i>Morgan</i> .....	\$ .....
..... O'head .....	\$ .....
	\$ 35.52

76

St. East

Pt. Tremont

Ave. No. 21

---

Name of Owner William J. Finch

---

Labor and Mat'l. Report Oct 16 1948

---

● Curb Box

---

6 Main

Elev. of Main at tap 6

---

Gate at ●

● Gate at

3/4" Copper 28' to main

---

● Curb Box

---

LSM-5C 5 15-48