

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
1	Lead	Cock	3/4"	\$
1	Curb	Valve	3/4" in.	\$
		T. S. & V.		\$
1	Service box	Short 3 1/2 x 4 1/2		\$
	Old returned	Long 4 1/2 x 5 1/2		\$
		Buff or Rdway		\$
33	Ft.	Copper		\$
31 1/8	in.	G. I.	Pipe at	\$
		G. I.		\$
	Nipples	in.	at	\$
	Bushings	to	in. at	\$
	Red'g			\$
	Inc'g	Coupl'gs	to in. at	\$
	Union	in.	at	\$
	Meter	in.	at	\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man	—1 at		\$
	Hrs. Water Maint. Man	—2 at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Gifford & Co.			\$
				\$
				\$
	O'head			\$
				\$

V

St. East Trenton Pl. 37E Ave. No. 37E

Name of Owner Eggleston

Labor and Mat'l. Report Sept 19 1957

6" Main Tap on Faxon St. Elev. of Main at tap 6"

Gate at • Gate at

3' 8" to main

• Curb Box

TAX ID# 309.116-17-1

LSM-SC-2-5 56