


LABOR AND MATERIALS

1 Copper } Connection 3/4 \$ 280  
 Lead }  
 1 Curb } Clock Valve } 3/4 in. \$ 360  
 T. S. & V. }  
 1 Service box } Short 3/4 X 4/4 } 580  
 Old returned } Long 4/4 X 5/4 }  
 Buff or Rdway }  
 2 Ft. 3/4 in. } Copper } Pipe at 35 \$  
 Galv. Iron }  
 Cast Iron }  
 Nipples ..... in. at ..... \$  
 Bushings ..... to ..... in. at ..... \$  
 Red'g } Couplings ..... to ..... in. at ..... \$  
 Inc'g }  
 Union ..... in. at ..... \$  
 Meter ..... in. at ..... \$  
 Lead Joints at ..... \$  
 Compound Joints at ..... \$  
 Hrs. Foreman at ..... \$  
 Hrs. Chauffeur at ..... \$  
 Hrs. Tapper at ..... \$  
 Hrs. Labor at ..... \$  
 Hrs. Labor at ..... \$  
 Hrs. Compressor at ..... \$  
 Compensation Ins. ..... \$  
 Trucking ..... \$ 100  
 Builders Use of Water ..... \$  
 Top by *Winosmiv* ..... \$  
 ..... \$  
 ..... \$  
 ..... \$  
 ..... \$

East, ✓ 5  
 Trammont  
 St. Pl. Ave. No. 15  
 Name of Owner Ida Rivers.  
 King  
 Labor and Mat'l. Report Sept 18 1907  
  
 6 Main Elev. of Main at tap 5  
 Gate at • Gate at  
 3/4" Copper 8' to main  
 • Curb Box  
 TAX ID # 309.16-17-13  
 LSM-5C-6-1-45