

Labor and Materials

1	Copper } Connection $3/4$	\$ 2.60	
	Lead		
1	Curb } Cock Valve } $3/4$ in.	\$ 2.27	
	T.S. & V.		
1	Service Box } Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$ 1.59	
	Old-retained } Long $4\frac{1}{2} \times 5\frac{1}{2}$		
		Buff. or Rdway	
25	Ft. $3/4$ in. } Copper	\$ 4.50	
			Galv. Iron } Pipe at
		Cast Iron	
	Nipples in. at	\$	
	Bushings to in. at	\$	
	Red'g } Couplings to in. at	\$	
	Inc'g		
	Union in. at	\$	
	Meter in. at	\$	
	Lbs. Br. Stone at	\$	
	Lbs. Sand at	\$	
	Bags Cement at	\$	
	Paving Brick } Mack } at	\$	
			Red
			Asphalt
	Lead Joints at	\$	
	Leadite Joints at	\$	
3	Hrs. Foreman at	\$ 1.88	
16	Hrs. Common Labor at	\$ 7.20	
	Hrs. Common Labor at	\$	
	Hrs. Mason at	\$	
	Hrs. Mason's Helper at	\$	
	Hrs. Compressor at	\$	
	Compensation Ins	\$ 28	
	Trucking	\$ 1.-	
	Builders' Use of Water	\$	
Total		\$ 21.32	

31-25

Labor and Material Report

May 21

19 21

Turnout 25 Hours from State st
 West 0 → Property line ← 03' out
 6' 4" 4' 4"

Harry Morgan

● Curb Box

6 Main

Elev of Main at tap 44.1/2

Gate at ●

● Gate at

● Curb Box

New tap