

**Labor and Materials**

Lead	Copper	Connection	3/4	\$ 2.70
	Curb	Cock Valve	3	\$ 7.39
		T.S. & V.	1/4	
	Service Box	Short 3/4x1 1/2		\$ 1.45
	Old returned	Long 4 1/2x5 1/2		
		Buff. or Rdway		
1/4	Ft.	Copper Galv. Iron	3	\$ 2.97
		Pipe at	1/4	
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
3	Hrs. Foreman	at		\$ 1.88
16	Hrs. Common Labor	at		\$ 7.20
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ .28
	Trucking			\$ 1 -
	Builders' Use of Water			\$ 5 -
Total \$				24.87

30-1A1

22

Labor and Material Report

19

15 Union St.

22



Curb Box

4 Main

Elev of Main at tap

Gate at

Gate at

11' to MAIN

Curb Box

Old tap disconnected.

This House Razed

1965