

### Labor and Materials

Copper	}	Connection.....	.....	\$	
Lead					
Curb	}	Cock Valve T. S. & V. ....	..... in	.....	\$
Service Box					
Old returned					
	}	Short 3½ x 4½	.....	\$	
		Long 4½ x 5½			
		Buff. or Rdway			
Ft. .... in.	}	Copper	Pipe at .....	\$	
		Galv Iron			
		Cast Iron			
Nipples .....	in. at .....			\$	
Bushings .....	to .....	in. at .....		\$	
Red'g	}	Conplings .....	to .....	in. at .....	\$
Inc'g					
Union .....	in. at .....			\$	
Meter .....	in. at .....			\$	
Lead Joints at .....				\$	
Leadite Joints at .....				\$	
Hrs. Foreman at .....				\$	
Hrs. Chauffeur at .....				\$	
Hrs. Tapper at .....				\$	
Hrs. Labor at .....				\$	
Hrs. Labor at .....				\$	
Hrs. Compressor at .....				\$	
Compensation Ins. ....				\$	
Trucking .....				\$	
Builders Use of Water .....				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	

old no. 11  
 St. \_\_\_\_\_  
 Pl. \_\_\_\_\_  
 Ave. No. 22 1/2

---

Name of Owner  
Paul W. Williams

---

Labor and Mat'l. Report 11-29-22 19

11

7'3" 29'6"  
 ● Curb Box

---

.....Main Elev. of Main at tap.....

---

Gate at ● ● Gate at

---

● Curb Box