

LABOR AND MATERIALS

1	Copper Lead	} Connection	$\frac{3}{4}$		\$ 1.35
1	Curb	{ Cock Valve F. S. & V.	$\frac{3}{4}$	in.	\$ 1.80
1	Service Box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buffer Rdway			\$ 1.70
9	Ft.	{ Copper Galv Iron Cast Iron	$\frac{3}{4}$	in. } Pipe at 18	\$ 1.62
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	{ Couplings	to	in. at	\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Leadite Joints at				\$
	Hrs. Foreman at				\$
3	Hrs. Chauffeur at		62 $\frac{1}{2}$		\$ 1.88
4	Hrs. Tapper at				\$ 2.50
4	Hrs. Labor at		45		\$ 1.80
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins.				\$.19
	Trucking				\$ 1.50
	Builders Use of Water	Patch			\$ 5.00
	Tap by Hessel				\$
					\$
					\$
					\$
					\$ 18.84

7 2 1941

St. 16
Pl. _____
Ave. No. 19

Name of Owner

Robinson

Labor and Mat'l. Report

Apr 18 1941



*4 Gal
Main*

Elev. of
Main at tap 5

Gate at ●

● Gate at

9' to main

This Place ● Curb Box

Razed

*Disconnected from
main July 65*

(to be Billed)