

Labor and Materials		
1	Lead Connection	\$.
1	Curb Cock	\$.
1	Service Box (Short 3 1/2 x 4)	\$.
	Old returned Buffalo	\$.
6	Ft. 1/2 in. G. I. Pipe at	\$.
	Nipples in. at	\$.
	Bushings to in. at	\$.
	Red'g Coup. to in. at	\$.
	Inc'g Coup. to in. at	\$.
	Union in. at	\$.
	Meter in. at	\$.
	Cu. Yds. Br. Stone at	\$.
	Cu. Yds. Sand at	\$.
	Bags Cement at	\$.
	Paving Brick { Mack Red Asphalt } at	\$.
2	Hrs. Foreman at	\$.
17	Hrs. Common Labor at	\$.
	Hrs. Mason at	\$.
	Hrs. at	\$.
	Hrs. at	\$.
9.00	Builders' Use of Water	\$.
	at	\$.
	Truck 100	\$.
	at	\$.
	at	\$.
	at	\$.
	Total	\$ 15.00

13 April 1925  
 Labor and Material Report 13

White St Tap on Harlem St

3'-9 1/2" Curb Box

measured in from  
 6 Main Elev. of Main at tap 5

Gate at 3/4" LEAD Gate at 6' to main

TAX ID # 302.20-13-9 Curb Box

Old tap to be dug up  
 dug up. April 16-25  
 7 hrs labor