

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$	2.71
1	Curb	Cock Valve T.S. & V.	3/4 in.	\$	3.83
1	Service box	Short 3 1/2 x 4 1/2		\$	4.69
	Old returned	Long 4 1/2 x 5 1/2		\$	
		Buff or Rdway		\$	
20	Ft. 3/4 in.	Copper G.I. Pipe at	45	\$	9.00
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1	at		\$	
17	Hrs. Water Maint. Man-2	at	1.24	\$	14.88
	Hrs. Garage Foreman	at		\$	
24	Hrs. Labor	at	1.13	\$	27.12
	Hrs. Compressor	at		\$	
	Compensation Ins.	at \$5.686 per C		\$	2.39
	Trucking			\$	1.50
	Pav't Patch			\$	14.40
	Tap by Gifford			\$	
	12-6-55			\$	
	O'head			\$	
				\$	80.52

St. Wait  
 -Pl. 6  
 Ave. No. 6

Name of Owner Paul Lavine

Labor and Mat'l. Report Dec. 6 1955

6" Main Elev. of Main at tap 5'

Gate at • Gate at •

3/4" Copper 20' to MAIN

• Curb Box

Old Tap DISCONNECTED at MAIN.