

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
	Lead			
1	Curb	Cock Valve T.S. & V.	3/4 in. oriseal	\$
1	Service box	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway }		\$
	Old returned			
18	Ft. 3/4 in.	Copper G.I. C.I.	Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins. at \$	per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Lareau & Co.			\$
	Dec. 13-66.			\$
	O'head			\$

Wallace St. 7  
 Faber Pl. Ave. No. 1  
 Name of Owner John Wheeler,

Labor and Mat'l. Report Dec. 13 1966



6" Main Elev. of Main at tap 4'

Gate at • Gate at •  
 3/4" Copper 18' to main  
 • Curb Box

TAX ID # 303.13-6-4