

Labor and Materials

1	Copper Lead	Connection $3/4"$	\$ 3.20
1	Curb	Cock Valve T-S. & V. $3/4"$ in.	\$ 1.00
1	Service Box	Short $3 1/2 \times 4 1/2$	\$ 1.30
	Old returned	Long $4 1/2 \times 5 1/2$ Buff. or Rdway	
25	Ft. $3/4"$ in.	Copper Galv. Iron } Pipe at	\$ 4.84
		Cast Iron }	
	Nipples	in. at	\$
	Bushings	to in. at	\$
1	Red g. Inc'g	Couplings $3/4"$ to $1"$ in. at	\$ 1.50
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	Mack Red Asphalt } at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
1	Hrs. Foreman	at 6.24	\$ 6.30
4	Hrs. Common Labor	at 20.78	\$ 83.12
	Hrs. Common Labor	at	\$
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$ 0.60
	Trucking		\$ 1.00
	Builders' Use of Water		\$

COPPER ADDED
7-21-2003

Total \$ 137.81

28-40
Labor and Material Report May 21 1928

$3/4"$ tap at 26 Walnut st



4" Main Elev. of Main at tap $4 1/2$

Gate at $3/4"$ Copper 25' to MAIN Gate at

● Curb Box

Old tap shut off
TAX ID # 303.17-11-9