

Labor and Materials

| | | | |
|----------------|---|--------------------------|----------|
| 1 | Copper } Connection..... | ? | \$ 3.70 |
| | Lead } | | |
| 1 | Curb } Cock } | 5 | \$ 1.00 |
| | Valve } | | |
| | T. S. & V. } | 4 | |
| 1 | Service Box } Short 3 1/2 x 4 1/2 } | | \$ 1.30 |
| | Old returned } Long 4 1/2 x 5 1/2 } | | |
| | | Buff. or Rdway | |
| 2 3/4 | Ft. } 1/2 in. } Copper } Pipe at..... | | \$ 50.5 |
| | | Galv. Iron | |
| | | Cast Iron | |
| | Nipples..... | in. at..... | \$ |
| 1 | Bushings..... | 2 1/2 to 1/2 in. at..... | \$ 1.5 |
| 1 | Red } Couplings..... | 1/2 to 1/4 in. at..... | \$ 1.0 |
| | Inc. } | | |
| | Union..... | in. at..... | \$ |
| | Meter..... | in. at..... | \$ |
| | Lbs. Br. Stone at..... | | \$ |
| | Lbs. Sand at..... | | \$ |
| | Bags Cement at..... | | \$ |
| | Paving Brick } Mack } at..... | | \$ |
| | | Red Asphalt | |
| | Lead Joints at..... | | \$ |
| | Leadite Joints at..... | | \$ |
| 2 | Hrs. Foreman at..... | | \$ 1.25 |
| 7 | Hrs. Common Labor at..... | 75.9 | \$ 2.84 |
| 7 | Hrs. Common Labor at..... | | \$ 3.00 |
| | Hrs. Mason at..... | | \$ |
| | Hrs. Mason's Helper at..... | | \$ |
| | Hrs. Compressor at..... | | \$ |
| | Compensation Ins..... | | \$ 2.0 |
| | Trucking..... | | \$ 1.00 |
| | Builders' Use of Water..... | | \$ |
| Total \$ 19.60 | | | |

Labor and Material Report

19 38

no 36-38 Walnut St



Main

Elev. of Main at tap 5

Gate at ● 3/4" copper 23' to MAIN ● Gate at

● Curb Box

Handwritten notes:
 Off top to
 Be dug up

TAX ID # 303.17-2-2