

Labor and Materials

1	Copper	Connection	$\frac{3}{4}$	\$	3.20
1	Curb	Cock	$\frac{3}{4}$ in.	\$	1.50
1	Service Box	Short 3" x 4"		\$	1.30
	Old returned	Buff. or Rdway		\$	
9	Ft.	Copper	Pipe at $\frac{3}{4}$	\$	1.98
2	Nipples	in. at $\frac{1}{2}$		\$	1.20
1	Bushings	to $\frac{1}{2}$ in. at $\frac{3}{4}$		\$	1.07
	Red'g	Couplings	to in. at	\$	
	Inc'g			\$	
2	Meters	in. at		\$	1.30
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	{ Mack Red Asphalt }	at	\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
5	Hrs. Foreman	at	0.21.5	\$	3.12
	Hrs. Common Labor	at		\$	
14	Hrs. Common Labor	at	40.17	\$	5.68
	Hrs. Mason	at		\$	
	Hrs. Mason's Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.			\$	1.23
	Trucking			\$	1.50
	Builders' Use of Water			\$	
				Total	\$ 18.08

27-60 37
 Labor and Material Report May 28 19 27

39 Walnut St



4 Main Elev. of Main at tap 4 1/2

Gate at 3/4" copper 9' to MAIN Gate at

Curb Box

TAX ID # 303.17-3-9