

Labor and Materials

1	Copper	Connection	3/4"	\$ 1.25
1	Lead			
1	Curb	Cock Valve T.S.&V.	3/4" in	\$ 1.70
1	Service Box	Short 3 1/2 x 4 1/2		\$ 1.45
	Old returned	Long 4 1/2 x 5 1/2	Buff. or Rdway	
1 1/2	Ft.	Copper Galv. Iron Cast Iron	Pipe at 1 3/4"	\$ 1.49
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
3	Hrs. Foreman	at	6.75	\$ 1.82
17	Hrs. Common Labor	at	4.5	\$ 5.40
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Masons Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$ 26
	Trucking			\$ 1.00
	Builders Use of Water	Patch		\$ 5.00
Total				\$ 19.65

1935-96

Labor and Material Report

1935

3/4 tap at 59 Walnut St



4 Main

Elev. of Main at tap 5 ft

Gate at

3/4 Copper

11' to main Gate at

● Curb Box

Old tap shut off at main

TAX ID # 303.17-3-5