

Labor and Materials

1	Lead Connection	3/4	\$
1	Curb Cock	3/4	\$
	Service Box	{ Short 3 1/2 x 4 1/2	\$
	Old returned	{ Long 4 1/2 x 5 1/2	\$
		Buffalo	\$
1	Ft. in C.I. Pipe at	4 1/2	\$
7	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Coup	to in. at	\$
	Inc'g Coup	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Cu. Yds. Br. Stone	at	\$
	Cu. Yds. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	{ Mack	\$
		{ Red	\$
		{ Asphalt	\$
	Hrs. Foreman	at	\$
7	Hrs. Common Labor	at	\$
	Hrs. Mason	at	\$
	Hrs.	at	\$
	Hrs.	at	\$
1/2	Builders' Use of Water	at	\$
	Track	1.00 at	\$
		at	\$
		at	\$
		at	\$
	Total	\$	\$

Labor and Material Report *Sept 9 1925*

3/4" tap at 6J Walnut st



TAX ID # 303.13-18-5

Main Elev. of Main at tap *44.1*

Gate at ● *4' 10" to main* ● Gate at

● Curb Box

19

David Roop
Renewal Day 6/87