

Labor and Materials

1	Copper } Connection		\$ 3.20
	Lead }		
1	Curb } Cock Valve	3 in.	\$ 1.00
	} T. S. & V. }		
1	Service Box } Short 3 1/2 x 4 1/2		\$ 1.30
25	Old returned } Long 4 1/2 x 5 1/2		
	} Buff. or Rdway }		
1	25 Ft. } Copper } Galv. Iron } Cast Iron } Pipe at		\$ 4.62
	Nipples	in. at	\$
1	Bushings	to in. at	\$ 1.10
1	Redg } Couplings	to in. at	\$.15
	Incg }		
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick } Mack } Red } Asphalt } at		\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
2	Hrs. Foreman	6 1/2	\$ 1.25
2	Hrs. Common Labor	50	\$ 1.00
19	Hrs. Common Labor	40 1/8	\$ 7.72
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$ 2.6
	Trucking		\$ 1.00
	Builders' Use of Water		\$

Total \$ 21.60

28-36

Labor and Material Report May 11 1928

for 70 gallons



Main Elev. of Main at tap 5

Gate at 3/4" copper 28' to main Gate at

● Curb Box

Get Top shut off

TAX ID# 303.13-17-7