

87-1938

St. Warren
Pl. 251
Ave. No. 153

Name of Owner
Cutshall

Labor and Mat'l. Report June 28 1938

see below.

251 1938

125.5 187.0

● Curb Box

10 Main Elev. of Main at tap 5

Gate at ● Gate at ●

36' to main

71.8 87.2

1" Stop
use yellow
T wrench
1968

● Curb Box

251 Warren St.
New

St. Warren
Pl. 251
Ave. No. 251

Name of Owner
Avery Cleaners

Labor and Mat'l. Report June 19 86

251

67'4" 85'6"

● Curb Box

Main Elev. of Main at tap

Gate at ● Gate at ●

TAX ID # 310.6-1-24

● Curb Box

LSM-SC-6-1-67

Labor and Materials

1	Copper Lead	Connection 1"	\$ 7.40
1	Curb	Cock Valve T. S. & V. } 1" in	\$ 9.47
1	Service Box Old returned	Short - 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	\$ 1.75
36	Ft. 1" in.	Copper Galv-Iron-Cast-Iron } Pipe at 27	\$ 9.72
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	Conplings to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
	Hrs. Foreman	at	\$
10	Hrs. Chauffeur	at 6.25	\$ 6.25
11	Hrs. Tapper	at 6.42	\$ 6.42
34	Hrs. Labor	at 45	\$ 15.30
	Hrs. Labor	at	\$
4	Hrs. Compressor	at 8.75	\$ 3.50
	Compensation Ins.		\$.27
	Trucking		\$ 1.00
	Builders Use of Water		\$
	Tap by Messell		\$
	Patch (sewer)		\$ 9.00
			\$
			\$ 71.14

LABOR AND MATERIALS

Copper Lead	Connection	\$
Curb	Cock Valve T. S. & V. } in.	\$
Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway	\$
Ft. 2 in.	Copper C.I. } Pipe at	\$
Nipples	in. at	\$
Bushings	to in. at	\$
Red'g Inc'g	Coupl'gs to in. at	\$
Union	in. at	\$
Meter	in. at	\$
Lead Joints	at	\$
Compound Joints	at	\$
Maintenance Foreman		\$
Hrs. Water Maint. Man-1	at	\$
Hrs. Water Maint. Man-2	at	\$
Hrs. Garage Foreman	at	\$
Hrs. Labor	at	\$
Hrs. Compressor	at	\$
Compensation Ins.	at \$ per C	\$
Trucking		\$
Pav't Patch		\$
		\$
		\$
		\$
O'head		\$
		\$