

LABOR AND MATERIALS

| | | | | | |
|-----------------------|---|---------------------|-----------|----|----|
| Copper | } | Connection | | \$ | |
| Lead | | | | | |
| Curb | { | Cock Valve | in. | | \$ |
| | | T. S. & V. | | | |
| Service Box | { | Short 3 1/2 x 4 1/2 | | | \$ |
| Old returned | | Long 4 1/2 x 5 1/2 | | | |
| | | Buff. or Rdway | | | |
| Ft. | } | { | in. | | \$ |
| | | Copper | | | |
| | | Galv Iron | | | |
| | | Cast Iron | Pipe at | | |
| Nipples | | | in. at | | \$ |
| Bushings | | | to in. at | | \$ |
| Red'g Inc'g | { | Couplings | to in. at | | \$ |
| | | | | | |
| Union | | | in. at | | \$ |
| Meter | | | in. at | | \$ |
| Lead Joints | | | at | | \$ |
| Leadite Joints | | | at | | \$ |
| Hrs. Foreman | | | at | | \$ |
| Hrs. Chauffeur | | | at | | \$ |
| Hrs. Tapper | | | at | | \$ |
| Hrs. Labor | | | at | | \$ |
| Hrs. Labor | | | at | | \$ |
| Hrs. Compressor | | | at | | \$ |
| Compensation Ins. | | | | | \$ |
| Trucking | | | | | \$ |
| Builders Use of Water | | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |

St. 18
 Pl. 16
 Ave. No. 16

Warren _____

Name of Owner
 Lemon Thomson Realty Corp.

Labor and Mat'l. Report 8-26827-20 19

10 Main
Elev. of Main at tap 5

Gate at ●
● Gate at

● Curb Box