LABOR AND MATERIALS

1	Copper / Lead } Connection 3/4	$ 1.31
1	Curb { Cock / Valve / T. S. & V. } 3/4 in.	$ 1.75
1	Service Box Old returned { Short 3½x4½ / Long 4½x5½ / Buff. or Rdway }	$ 1.60
34	Ft. 3/4 in. { Copper / Galv Iron / Cast Iron } Pipe at 18	$ 6.12
	Nipples ____ in. at	$
	Bushings ____ to ____ in. at	$
	Red'g / Inc'g } Couplings ____ to ____ in. at	$
	Union ____ in. at	$
	Meter ____ in. at	$
	Lead Joints at	$
	Leadite Joints at	$
	Hrs. Foreman at	$
8	Hrs. Chauffeur at 62½	$ 5.—
15	Hrs. Tapper at	$ 9.38
15	Hrs. Labor at	$ 6.75
	Hrs. Labor at	$
5	Hrs. Compressor at 62½	$ 3.13
	Compensation Ins.	$ .65
	Trucking	$
	Builders Use of Water 2 Patches	$ 18.—
	Taply Miller	$
		$
		$
		$
		$ 53.69

9 7 - - 1940

St. 281
Pl.
Warren Ave. No. 183-185

Name of Owner
Hatz

Labor and Mat'l. Report Aug 27 1940

● Curb Box

8 Main

Elev. of Main at tap 7

Gate at ● 3/4" copper

● Gate at 34' to main

● Curb Box

TAX ID# 310.6-1-11