

LABOR AND MATERIALS

1	Copper	{ Connection	1"		\$ 560
	Lead				
	Curb	{ Cock Valve T. S. & V. }	in.		\$
	Service box	{ Short 3 1/2 x 4 1/2			
	Old returned	{ Long 4 1/2 x 5 1/2			
		{ Buff or Rdway			\$
	Ft.	{ Copper			
	in.	{ G. I.			
		{ C. I. }	Pipe at		\$
	Nipples	in.	at		\$
	Bushings	to	in. at		\$
	Red'g	{ Coupl'gs	to	in. at	\$
	Inc'g				\$
	Union	in.	at		\$
	Meter	in.	at		\$
	Lead Joints	at			\$
	Compound Joints	at			\$
2	Hrs. Water Maint. Man-1	at	1.38		\$ 276
2	Hrs. Water Maint. Man-2	at	1.27		\$ 254
	Hrs. Labor	at			\$
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.	at \$	per C.		\$
	Trucking				\$
	Pav't Patch				\$
	Trucking				\$ 1.00
	Equip. 50. Old Conn.				\$ 2000
	O'head				\$
	Tap by Miller				\$ 31.90
	7-26-51				

V

St. Warren
Ave. No. 313

Name of Owner
Glens Falls Cement Co.

Labor and Mat'l. Report July 26 1951

6" Main Elev. of Main at tap 6'

Gate at ● ● Gate at

This tap measured on
from East Side of Office

● Curb Box

Old tap disconnected
ON WARREN ST.

1" Copper

LSM-5C 10-21-50