

Labor and Materials

1	Copper	} Connection. 1 1/2	7.40
	Board			
1	Curb	} 1 1/2 in	5.78
	{ Cock Valve T.S.&V.			
	Service Box	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	1.54
	Old returned			
12	Ft. 1 1/2 in.	{ Copper Galv. Iron Cast Iron	Pipe at 7.1	3.48
	Nipples	in. at	\$
	Bushings	to	in. at
	Red'g Inc'g	{ Couplings to	in. at
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	{ Mack Red Asphalt	at
	Lead Joints			
	Leadite Joints	at	\$
3	Hrs. Foreman	at	6.25	1.88
	Hrs. Common Labor	at	\$
	Hrs. Common Labor	at	\$
	Hrs. Mason	at	\$
	Hrs. Masons Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins	9.07	\$
	Trucking	1.00	\$
	Builders Use of Water	Per. Rate	2.50	\$
Total				23.65

101 34
Labor and Material Report 10/3/34 19

45-49 Warren St.
Empire Garage

77

W. J. St.

● Curb Box

Main

Elev. of Main at tap 5

Gate at ●

1 1/2"

32'

12' to main

● Curb Box

10
Empire Storage

TAX ID # 310.53-10

Post office

VM