

LABOR AND MATERIALS

Copper	} Connection	_____	\$	_____	
Lead		_____	\$	_____	
Curb	} Cock Valve T.S. & V.	_____ in.	\$	_____	
Service box		} Short 3½ x 4½	_____	\$	_____
Old returned			} Long 4½ x 5½	_____	\$
Ft. <u>1</u> in.	} Copper G.I. G.I.	Pipe at _____		\$	_____
Nipples		_____ in. at _____	\$	_____	
Bushings	_____ to _____ in. at _____	\$	_____		
Red'g Inc'g	} Coupl'gs	_____ to _____ in. at _____	\$	_____	
Union		_____ in. at _____	\$	_____	
Meter	_____ in. at _____	\$	_____		
Compound Joints	at _____	\$	_____		
Maintenance Foreman	_____	\$	_____		
Hrs. Water Maint. Man	—1 at _____	\$	_____		
Hrs. Water Maint. Man	—2 at _____	\$	_____		
Hrs. Garage Foreman	_____ at _____	\$	_____		
Hrs. Labor	_____ at _____	\$	_____		
Hrs. Compressor	at _____	\$	_____		
Trucking	_____	\$	_____		
Pav't Patch	_____	\$	_____		
		\$	_____		
		\$	_____		
		\$	_____		
		\$	_____		
		\$	_____		
		\$	_____		

3

Waveren St. ~~Pl.~~ Ave. No. ~~3~~

Name of Owner
TAX ID # 310.5-2-5

Labor and Mat'l. Report 1986

47' 0" 31' 3" Curb Box RAMP Elev. of Main at tap

Gate at • Gate at •

• Curb Box

LSM-5C-6-1-67