

Labor and Materials

1...Copper } Connection. 3/4.....	\$ 1.48
1...Lead }	
1...Curb { Cock } 3/4...in	\$ 1.79
{ Valve }	
{ T.S.&V. }	
1...Service Box { Short 3 1/2 x 4 1/2 }	\$ 1.30
Old returned { Long 4 1/2 x 5 1/2 }	
{ Buff. or Rdway }	
8...Ft. 3/4 in. { Copper } Pipe at	\$ 1.44
{ Galv. Iron }	
{ Cast Iron }	
.....Nipplesin. at	\$
.....Bushingstoin. at	\$
.....Red'g } Couplings.....to.....in.at.....	\$
.....Inc'g }	
.....Union.....in. at	\$
.....Meter.....in. at	\$
.....Lbs. Br. Stone at	\$
.....Lbs. Sand at	\$
.....Bags Cement at	\$
.....Paving Brick { Mack } at	\$
{ Red }	
{ Asphalt }	
.....Lead Joints at	\$
.....Leadite Joints at	\$
17...Hrs. Foreman at	\$ 10.63
1...Hrs. Common Labor at	\$ 45
.....Hrs. Common Labor at	\$
.....Hrs. Mason at	\$
.....Hrs. Masons Helper at	\$
1...Hrs. Compressor at	\$ 88
.....Compensation Ins	\$ 1.34
.....Trucking	\$ 1
.....Builders Use of Water Patch	\$ 9.-
Total \$	28.31

32-77

Labor and Material Report 7/5/32 19

116
no 72 Warren st

78'3" 54'2"

● Curb Box

Shut off at Curb 8-16-72

10" Main Elev. of Main at tap 4 1/2'

● Gate at 10/22 - not on map ● Gate at

● Curb Box

Old taps shut off

5' to main

35'6"

10' ONYP MA hole

#122

OK 9/10