

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$	2.76
1	Lead				
1	Curb	Cock Valve T. S. & V.	3/4 in.	\$	3.49
1	Service box	Short 3 1/2 X 4 1/2			
	Old returned	Long 4 1/2 X 5 1/2			4.74
11	Ft.	Buff or Rdway		\$	
		Copper			
		G. I.	Pipe at	38	\$ 4.18
		G. I.			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g				
	Inc'g	Coupl'gs. to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Compound Joints at			\$	
	Hrs. Water Maint. Man-1 at			\$	
10	Hrs. Water Maint. Man-2 at	1.24		\$	12.40
21	Hrs. Labor-	at 1.13		\$	23.73
	Hrs. Labor-	at		\$	
	Hrs. Compressor at			\$	
	Compensation Ins. at	\$40.6 per C		\$	1.59
	Trucking			\$	1.00
	Pav't Patch			\$	12.32
	TAP by GISSORD 6-10-53			\$	
	O'head			\$	
				\$	166.21

53.89

St. Warren
Pl. 146
Ave. No. 146

Name of Owner Carter

Labor and Mat'l. Report June 10 1953

● Curb Box

10" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

3/4" copper 11' to main

● Curb Box

TAX ID # 303.17-21-13

LSM-5C 5 15-48