

LABOR AND MATERIALS

1	Copper	{ Connection	3/4"	\$	2.29
1	Lead	{ Cock			
		{ Valve	3/4 in.	\$	2.70
		{ T.S. & V.			
1	Service box	{ Short	3 1/2 x 4 1/2		
	Old returned	{ Long	4 1/2 x 5 1/2	\$	4.25
		{ Buff or Rdway			
11	Ft.	{ Copper		\$	3.85
	3/4 in.	{ G.I.	Pipe at		
		{ C.I.			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	{ Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Compound Joints at			\$	
1 1/2	Hrs. Water Maint. Man-1	at	1.12	\$	1.68
11	Hrs. Water Maint. Man-2	at	1.02	\$	11.22
26	Hrs. Labor	at	91	\$	23.66
	Hrs. Labor	at		\$	
2	Hrs. Compressor at		1.20	\$	2.40
	Compensation Ins. at \$	per C.		\$.81
	Trucking			\$	1.00
	Pav't Patch			\$	20.16
				\$	
				\$	
				\$	
	O'head			\$	
				\$	74.02

St.
Pt.
Warren Ave. No. 150

Name of Owner Donovan

Labor and Mat'l. Report July 10 1950

#150

56'9"

49'0"

● Curb Box

10" Main Elev. of Main at tap... 5'

Gate at ● Gate at ●

3/4" Copper 11' to main

● Curb Box

TAX ID # 303.17-21-14

LSM-5C 10-21-49